

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

EO716
East
> 1
1.012 mi.
5344 ft.

**FOUND STAINED SOIL WHILE DRILLING
NEPTUNE & CONEY ISLAND AVENUES
BROOKLYN, NY**

**NY Spills S108467166
N/A**

Site 3 of 8 in cluster EO

**Relative:
Higher**

**Actual:
9 ft.**

SPILLS:

Name: FOUND STAINED SOIL WHILE DRILLING
Address: NEPTUNE & CONEY ISLAND AVENUES
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0613972 / 2008-07-29
Facility ID: 0613972
Facility Type: ER
DER Facility ID: 328621
Site ID: 379127
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2007-03-29
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 2007-03-29
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2007-03-29
Spill Record Last Update: 2008-07-29
Spiller Name: ERTSDESK

Spiller Company: CON EDISON
Spiller Address: NEPTUNE & CONEY ISLAND AV
Spiller Company: 999
Contact Name: ERTSDESK
DEC Memo: "205141. see eDocs 5/15/07: spill submitted for closure by Con Edison. Sent back requesting information: Who conducted drilling? What is address of location where core samples were taken? This information is needed for NYSDEC to follow up with possible responsible party. (JHO) 6/15/07: According to Con ed (Lou Clark) location was 75 feet west of Coney Island Ave curblin, on Neptune Ave. and 5 feet south of curb on sidewalk on Neptune Ave. (JHO) 10/11/07: e-mail from Lou Clark: As per your request regarding EMIS 205141, attached is the subsurface report for borings Pro Solutions did for us at Coney Island Ave and Neptune Ave in Brooklyn. See eDocs for boring report. Spill referred to Spills program (R. Austin) for follow-up. (JHO) 7/29/08 - Austin - Analyticals not conclusive that a sig. petroleum problem exists - closed - end"

Remarks: "DRILLING FOR A NEW MANHOLE AND FOUND OIL; 205141"

All Materials:

Site ID: 379127
Operable Unit ID: 1136618
Operable Unit: 01
Material ID: 2126555

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported